

DECIMAL INCH

MILLIMETER

<p>NO LEADING ZERO <u>.5</u></p> <p>WHOLE NUMBER DIMENSIONS</p> <p><u>5.00</u> ZEROS MATCH TOLERANCE LEVEL</p>	<p>USE LEADING ZERO <u>0.5</u></p> <p>WHOLE NUMBER DIMENSIONS</p> <p><u>5</u> NO DECIMAL NO TRAILING ZERO</p> <p>NON-WHOLE NUMBERS</p> <p><u>5.2</u> NO TRAILING ZERO</p>
<p>UNILATERAL TOLERANCE</p> <p><u>.500</u> <u>+0.005</u> <u>-0.000</u></p> <p>SIGN ON THE ZERO MATCH ALL DECIMAL PLACES</p>	<p>UNILATERAL TOLERANCE</p> <p>21 <u>0</u> OR 21 <u>+0.02</u> <u>-0.02</u> <u>0</u></p> <p>NO SIGN ON THE ZERO</p>
<p>BILATERAL TOLERANCE</p> <p><u>.500</u> <u>+0.005</u> <u>-0.010</u></p> <p>MATCH ALL DECIMAL PLACES</p>	<p>BILATERAL TOLERANCE</p> <p>21 <u>+0.25</u> <u>-0.10</u></p> <p>MATCH DECIMAL PLACES OF TOLERANCE VALUES ONLY</p>
<p>LIMIT DIMENSIONS</p> <p><u>.750</u> <u>.752</u></p> <p>MATCH DECIMAL PLACES</p>	<p>LIMIT DIMENSIONS</p> <p><u>21.45</u> <u>21.00</u></p> <p>MATCH DECIMAL PLACES</p>
<p>BASIC DIMENSIONS</p> <p><u>1.00</u> DO NOT NEED TO MATCH</p> <p><u>Ø.005</u> A B C</p>	<p>BASIC DIMENSIONS</p> <p><u>25</u> FOLLOW DIMENSION RULES DO NOT NEED TO MATCH</p> <p><u>Ø 0.25</u> A B C</p>
<p>ANGLE DIMENSIONS</p> <p><u>30.0°</u> <u>± 0.2°</u></p> <p>MATCH DECIMAL PLACES</p>	